


INTERIM FLY QUIET SUMMARY

WEEK OF NOVEMBER 17, 2019 (Week 3)




Note: Values above represent the average for time period.

**INTERIM FLY QUIET RUNWAY ROTATION
NOVEMBER 3, 2019 TO JANUARY 31, 2021¹
WEEK OF NOVEMBER 17TH (WEEK 3)**




Fly Quiet Mode²

Time				Runway Rotation Adherence		
Start	Stop	Duration (hrs: mins)	Percentage of Nighttime ³	Primary Configuration ⁴	Secondary Configuration ⁴	Operations
11/17/19 - 10:47 PM	11/18/19 - 05:53 AM	7:06	79%	0%	77%	104
11/18/19 - 10:31 PM	11/19/19 - 05:47 AM	7:16	81%	0%	97%	111
11/19/19 - 10:32 PM	11/20/19 - 05:51 AM	7:19	81%	0%	96%	110
11/20/19 - 11:19 PM	11/21/19 - 05:21 AM	6:02	67%	51%	38%	79
11/21/19 - 10:52 PM	11/22/19 - 05:36 AM	6:44	75%	0%	95%	96
11/22/19 - 10:39 PM	11/23/19 - 05:54 AM	7:15	81%	36%	57%	114
11/23/19 - 11:38 PM	11/24/19 - 05:51 AM	6:13	69%	0%	21%	66
Average (Week of November 17th)						
10:54 PM	5:44 AM	6:50	76%	12%	73%	97



Notes:

- Interim Fly Quiet is a temporary program beginning November 3, 2019 through early 2021, when Runway 9R/27L is closed for extension construction. It is expected that significant runway construction, maintenance, and/or pavement rehabilitation on Runways 4L/22R and 4R/22L would impact the Interim Fly Quiet during the 2019 and 2020 construction seasons, respectively. It is not anticipated that the Interim Fly Quiet would occur during these construction periods.
- Fly Quiet Mode is the period of time in which the nighttime operations are operating in accordance with the CDA's Fly Quiet Program.
- FAR Part 150 considers nighttime hours 10:00 PM - 07:00 AM.
- Percentage of operations on designated runways within Fly Quiet Mode.
- Runway 10L/28R is available for flights that require additional runway length and have contacted CDA Operations at a minimum of 2 hours prior to arrival or departure.



Comments:

- a: There was 1 request granted for alternative runways during Fly Quiet Mode.
- b: On the night of 11/20, the Rotation was restricted due to inclement weather.
- c: On the night of 11/23, the Rotation was restricted due to rubber removal on Runway 10C/28C.