



INTERIM FLY QUIET SUMMARY

WEEK OF NOVEMBER 3, 2019 (Week 1)





Note: Values above represent the average for time period.

**INTERIM FLY QUIET RUNWAY ROTATION
NOVEMBER 3, 2019 TO JANUARY 31, 2021¹
WEEK OF NOVEMBER 3RD (WEEK 1)**



Fly Quiet Mode ²						
Time				Runway Rotation Adherence		
Start	Stop	Duration (hrs: mins)	Percentage of Nighttime ³	Primary Configuration ⁴	Secondary Configuration ⁴	Operations
11/3/19 - 10:34 PM	11/4/19 - 05:36 AM	7:02	78%	0%	66%	96
11/4/19 - 10:21 PM	11/5/19 - 05:42 AM	7:21	82%	0%	82%	110
11/5/19 - 10:39 PM	11/6/19 - 05:55 AM	7:16	81%	0%	39%	106
11/6/19 - 11:23 PM	11/7/19 - 03:11 AM	3:48	42%	66%	10%	58
11/7/19 - 10:46 PM	11/8/19 - 05:47 AM	7:01	78%	0%	79%	92
11/8/19 - 10:43 PM	11/9/19 - 05:39 AM	6:56	77%	0%	42%	90
11/9/19 - 10:06 PM	11/10/19 - 05:47 AM	7:41	85%	0%	73%	112
Average (Week of November 3rd)						
10:38 PM	5:22 AM	6:43	75%	6%	59%	95



Notes:

- Interim Fly Quiet is a temporary program beginning November 3, 2019 through early 2021, when Runway 9R/27L is closed for extension construction. It is expected that significant runway construction, maintenance, and/or pavement rehabilitation on Runways 4L/22R and 4R/22L would impact the Interim Fly Quiet during the 2019 and 2020 construction seasons, respectively. It is not anticipated that the Interim Fly Quiet would occur during these construction periods.
- Fly Quiet Mode is the period of time in which the nighttime operations are operating in accordance with the CDA's Fly Quiet Program.
- FAR Part 150 considers nighttime hours 10:00 PM - 07:00 AM.
- Percentage of operations on designated runways within Fly Quiet Mode.
- Runway 10L/28R is available for flights that require additional runway length and have contacted CDA Operations at a minimum of 2 hours prior to arrival or departure.

Comments:

- There were 5 requests granted for alternative runways during Fly Quiet Mode.
- On the nights of 11/3 and 11/5, the Rotation was restricted due to the FAA flight checks on runways for equipment maintenance and/or testing.
- On the night of 11/6, the Rotation was restricted due to inclement weather.
- On the night of 11/8, the Rotation was restricted due to construction on Runway 10C/28C.