


# INTERIM FLY QUIET SUMMARY

WEEK OF APRIL 19, 2020 (Week 25)




Note: Values above represent the average for time period.

[www.flychicago.com/oharenoise](http://www.flychicago.com/oharenoise)

**INTERIM FLY QUIET RUNWAY ROTATION  
NOVEMBER 3, 2019 TO JANUARY 31, 2021<sup>1</sup>  
WEEK OF APRIL 19TH (WEEK 25)**



Fly Quiet Mode <sup>2</sup>						
Time				Runway Rotation Adherence		
Start	Stop	Duration (hrs: mins)	Percentage of Nighttime <sup>3</sup>	Primary Configuration <sup>4</sup>	Secondary Configuration <sup>4</sup>	Operations
4/19/20 - 10:20 PM	4/20/20 - 06:10 AM	7:50	87%	40%	2%	48
4/20/20 - 10:32 PM	4/21/20 - 06:21 AM	7:49	87%	0%	16%	56
4/21/20 - 10:03 PM	4/22/20 - 07:00 AM	8:57	99%	9%	0%	81
4/22/20 - 10:10 PM	4/23/20 - 06:57 AM	8:47	98%	35%	0%	85
4/23/20 - 10:04 PM	4/24/20 - 06:08 AM	8:04	90%	56%	0%	52
4/24/20 - 10:00 PM	4/25/20 - 06:24 AM	8:24	93%	22%	0%	50
4/25/20 - 10:01 PM	4/26/20 - 06:51 AM	8:50	98%	40%	0%	68
Average (Week of April 19th)						
10:10 PM	6:33 AM	8:23	93%	28%	2%	63



**Notes:**

- Interim Fly Quiet is a temporary program beginning November 3, 2019 through early 2021, when Runway 9R/27L is closed for extension construction. It is expected that significant runway construction, maintenance, and/or pavement rehabilitation on Runways 4L/22R and 4R/22L would impact the Interim Fly Quiet during the 2019 and 2020 construction seasons, respectively. It is not anticipated that the Interim Fly Quiet would occur during these construction periods.
- Fly Quiet Mode is the period of time in which the nighttime operations are operating in accordance with the CDA's Fly Quiet Program.
- FAR Part 150 considers nighttime hours 10:00 PM - 07:00 AM.
- Percentage of operations on designated runways within Fly Quiet Mode.
- Runway 10L/28R is available for flights that require additional runway length and have contacted CDA Operations at a minimum of 2 hours prior to arrival or departure.



**Comments:**

- a: There were 12 requests granted for alternative runways during Fly Quiet Mode.
- b: On the night of 4/20, the Rotation was restricted due to inclement weather.
- c: On the night of 4/21, the Rotation was restricted due to FAA navigational aid maintenance on Runway 9R/27L.