


# INTERIM FLY QUIET SUMMARY

WEEK OF JANUARY 17, 2021 (WEEK 47)




Note: Values above represent the average for time period.

[www.flychicago.com/oharenoise](http://www.flychicago.com/oharenoise)

**INTERIM FLY QUIET RUNWAY ROTATION  
NOVEMBER 3, 2019 TO JANUARY 31, 2021<sup>1</sup>  
WEEK OF JANUARY 17TH (WEEK 47)**




Fly Quiet Mode <sup>2</sup>						
Time				Runway Rotation Adherence		
Start	Stop	Duration (hrs: mins)	Percentage of Nighttime <sup>3</sup>	Primary Configuration <sup>4</sup>	Secondary Configuration <sup>4</sup>	Operations
1/17/21 - 10:05 PM	1/18/21 - 06:44 AM	8:39	96%	0%	87%	76
1/18/21 - 10:00 PM	1/19/21 - 07:00 AM	9:00	100%	0%	93%	88
1/19/21 - 10:00 PM	1/20/21 - 06:36 AM	8:36	96%	0%	63%	82
1/20/21 - 10:03 PM	1/21/21 - 06:48 AM	8:45	97%	0%	95%	84
1/21/21 - 10:19 PM	1/22/21 - 05:40 AM	7:21	82%	0%	67%	63
1/22/21 - 10:02 PM	1/23/21 - 06:30 AM	8:28	94%	0%	47%	66
1/23/21 - 10:00 PM	1/24/21 - 06:43 AM	8:43	97%	76%	0%	67
Average (Week of January 17th)						
10:04 PM	6:34 AM	8:30	94%	10%	67%	75



**Notes:**

- 1: Interim Fly Quiet is a temporary program beginning November 3, 2019 through early 2021, when Runway 9R/27L is closed for extension construction.
- 2: Fly Quiet Mode is the period of time in which the nighttime operations are operating in accordance with the CDA's Fly Quiet Program.
- 3: FAR Part 150 considers nighttime hours 10:00 PM - 07:00 AM.
- 4: Percentage of operations on designated runways within Fly Quiet Mode.
- 5: Runway 10L/28R is available for flights that require additional runway length and have contacted CDA Operations at a minimum of 2 hours prior to arrival or departure.



**Comments:**

- a: There were 0 requests granted for alternative runways during Fly Quiet Mode.
- b: On the night of 1/19, the Rotation was restricted due to inclement weather.
- c: On the night of 1/21, the Rotation was restricted due to a disabled aircraft on Runway 10C/28C.
- d: On the night of 1/22, the Rotation was restricted due to FAA navigational aid maintenance on Runway 10L/28R.