


# INTERIM FLY QUIET SUMMARY

WEEK OF JANUARY 12, 2020 (Week 11)




Note: Values above represent the average for time period.

**INTERIM FLY QUIET RUNWAY ROTATION  
NOVEMBER 3, 2019 TO JANUARY 31, 2021<sup>1</sup>  
WEEK OF JANUARY 12TH (WEEK 11)**




Fly Quiet Mode <sup>2</sup>						
Time				Runway Rotation Adherence		
Start	Stop	Duration (hrs: mins)	Percentage of Nighttime <sup>3</sup>	Primary Configuration <sup>4</sup>	Secondary Configuration <sup>4</sup>	Operations
1/12/20 - 11:05 PM	1/13/20 - 06:19 AM	7:14	80%	0%	90%	129
1/13/20 - 10:47 PM	1/14/20 - 05:52 AM	7:05	79%	56%	33%	93
1/14/20 - 10:38 PM	1/15/20 - 06:10 AM	7:32	84%	45%	42%	114
1/15/20 - 11:43 PM	1/16/20 - 05:42 AM	5:59	66%	0%	86%	69
1/16/20 - 10:29 PM	1/17/20 - 06:01 AM	7:32	84%	35%	60%	112
1/18/20 - 12:17 AM	1/18/20 - 06:12 AM	5:55	66%	61%	0%	44
1/18/20 - 10:12 PM	1/19/20 - 06:08 AM	7:56	88%	0%	89%	99
Average (Week of January 12th)						
11:01 PM	6:03 AM	7:02	78%	26%	62%	94



**Notes:**

- Interim Fly Quiet is a temporary program beginning November 3, 2019 through early 2021, when Runway 9R/27L is closed for extension construction. It is expected that significant runway construction, maintenance, and/or pavement rehabilitation on Runways 4L/22R and 4R/22L would impact the Interim Fly Quiet during the 2019 and 2020 construction seasons, respectively. It is not anticipated that the Interim Fly Quiet would occur during these construction periods.
- Fly Quiet Mode is the period of time in which the nighttime operations are operating in accordance with the CDA's Fly Quiet Program.
- FAR Part 150 considers nighttime hours 10:00 PM - 07:00 AM.
- Percentage of operations on designated runways within Fly Quiet Mode.
- Runway 10L/28R is available for flights that require additional runway length and have contacted CDA Operations at a minimum of 2 hours prior to arrival or departure.



**Comments:**

- There were 0 requests granted for alternative runways during Fly Quiet Mode.
- On the night of 1/17, Fly Quiet Mode was restricted due to inclement weather.