


INTERIM FLY QUIET SUMMARY

WEEK OF JANUARY 19, 2020 (Week 12)



Note: Values above represent the average for time period.


**INTERIM FLY QUIET RUNWAY ROTATION
NOVEMBER 3, 2019 TO JANUARY 31, 2021¹
WEEK OF JANUARY 19TH (WEEK 12)**




Fly Quiet Mode²

Time				Runway Rotation Adherence		
Start	Stop	Duration (hrs: mins)	Percentage of Nighttime ³	Primary Configuration ⁴	Secondary Configuration ⁴	Operations
1/19/20 - 10:51 PM	1/20/20 - 06:08 AM	7:17	81%	36%	3%	89
1/20/20 - 11:09 PM	1/21/20 - 05:43 AM	6:34	73%	0%	56%	72
1/21/20 - 10:08 PM	1/22/20 - 05:51 AM	7:43	86%	0%	44%	115
1/22/20 - 10:55 PM	1/23/20 - 05:58 AM	7:03	78%	0%	1%	99
1/23/20 - 11:21 PM	1/24/20 - 06:07 AM	6:46	75%	0%	2%	99
1/24/20 - 10:43 PM	1/25/20 - 05:42 AM	6:59	78%	0%	2%	93
1/25/20 - 11:17 PM	1/26/20 - 05:30 AM	6:13	69%	0%	2%	49
Average (Week of January 19th)						
10:54 PM	5:51 AM	6:57	77%	5%	16%	88

Primary⁵




Secondary⁵



Notes:

- Interim Fly Quiet is a temporary program beginning November 3, 2019 through early 2021, when Runway 9R/27L is closed for extension construction. It is expected that significant runway construction, maintenance, and/or pavement rehabilitation on Runways 4L/22R and 4R/22L would impact the Interim Fly Quiet during the 2019 and 2020 construction seasons, respectively. It is not anticipated that the Interim Fly Quiet would occur during these construction periods.
- Fly Quiet Mode is the period of time in which the nighttime operations are operating in accordance with the CDA's Fly Quiet Program.
- FAR Part 150 considers nighttime hours 10:00 PM - 07:00 AM.
- Percentage of operations on designated runways within Fly Quiet Mode.
- Runway 10L/28R is available for flights that require additional runway length and have contacted CDA Operations at a minimum of 2 hours prior to arrival or departure.



Comments:

- There were 5 requests granted for alternative runways during Fly Quiet Mode.
- On the nights of 1/22, 1/23, 1/24, and 1/25 the Rotation was restricted due to inclement weather.